


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

30-015-05183

Release Notification and Corrective Action

NMLB1129437031

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: LINN Energy	Contact: Joe Hernandez
Address: 2130 W Bender Blvd. - Hobbs, NM	Telephone No.: 575-942-8675
Facility Name: Turner B 4	Facility Type: Injection Well

Surface Owner: BLM	Mineral Owner: BLM	Lease No.: NM LC 029395-B
--------------------	--------------------	---------------------------

LOCATION OF RELEASE

Unit Letter N	Section 17	Township 17S	Range 31E	Feet from the 660	North/South Line S	Feet from the 1980	East/West Line E	County Eddy
-------------------------	---------------	-----------------	--------------	----------------------	-----------------------	-----------------------	---------------------	----------------

Latitude: 32 49" 44.9" Longitude: -103 53' 38.8"

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 30	Volume Recovered: 10
Source of Release: Overflow	Date and Hour of Occurrence:	Date and Hour of Discovery:
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? T. Gregston, BLM - M. Bratcher NMOC D	
By Whom? J. Hernandez	Date and Hour: 11/14/11 - 0800	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Flowing back well into tank, tank overflowed. Well was shut in until tank could be emptied.

Describe Area Affected and Cleanup Action Taken.*: Spill area is on pad and pasture, approximately 300' long with an average width of 20'. Full assessment and corrective action plan is pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Jose Hernandez	Signed By:	
Title: Foreman	Approval Date: OCT 21 2011	Expiration Date:
E-mail Address: jhernandez@linneenrgy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/14/11	Phone: 575-738-1739	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
11/21/2011

2RP-933