

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

OCT 14 2011

NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-28984

Release Notification and Corrective Action

nMLB 1129440331

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: LINN Energy	269324	Contact: Joe Hernandez
Address: 2130 W Bender Blvd. - Hobbs, NM		Telephone No.: 575-942-8675
Facility Name: Turner B South #108		Facility Type: Producing Oil Well

Surface Owner: BLM	Mineral Owner: BLM	Lease No.: 3001528984
--------------------	--------------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	30	17S	31E	2190	S	1700	W	Eddy

Latitude: 32 48' 22.018" Longitude: -103 54' 21.284"

NATURE OF RELEASE

Type of Release: Oil & reduced Water	Volume of Release: 50 bbls	Volume Recovered: 25 bbls
Source of Release: <u>Flowline</u>	Date and Hour of Occurrence: 09/28/11-1500	Date and Hour of Discovery: 09/28/11-1530
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? T. Gregston, BLM, M. Bratcher NMOCD	
By Whom? Fred Holmes	Date and Hour: 09/29/11-0730	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Line over-pressured causing line to leak. Well was shut in and repairs made of the line.

Describe Area Affected and Cleanup Action Taken.*: Release covers approximately 3600 square feet of surface area. Approximately 70% is on the lease road. the remainder is confined to pasture adjacent to the road area. Corrective action plan is pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Joe Hernandez</u>	Approved by <u>M. Bratcher</u> District Supervisor	
Printed Name: Jose Hernandez	Approval <u>OCT 21 2011</u> Expiration Date:	
Title: Foreman	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: jhernandez@linneenergy.com		
Date: 10/14/11 Phone: 575-738-1739		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
11/21/2011

2RP-935