


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB/129337355 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC #29/37	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Electra Federal North Tank Battery	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-36467

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	10	17S	30E					Eddy

Latitude 32.85309 Longitude 103.95885

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	60bbls	Volume Recovered	50bbls
Source of Release	Oil tank	Date and Hour of Occurrence	09/26/2011	Date and Hour of Discovery	09/26/2011 7:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD Jim Amos-OCD		
By Whom?	Josh Russo	Date and Hour	09/26/2011 5:52 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The equalizer valve was closed causing the oil tank to overflow. The equalizer line has been opened and there will be closer inspection of equalizer valves in the future.

Describe Area Affected and Cleanup Action Taken.*

Initially 60bbls of oil were released from the oil tank and we were able to recover 50bbls with a vacuum truck. The entire release was completely contained inside the facility walls of the tank battery. All free fluid has been recovered and the tank has been steam cleaned. Contaminated soil inside the facility has been removed and sent to disposal. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Signed By:  Approved by District Supervisor:	
Title: HSE Coordinator	Approval Date: OCT 20 2011	Expiration Date:
E-mail Address: jrusso@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/06/2011 Phone: 432-212-2399	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>11/20/2011</u>	

* Attach Additional Sheets If Necessary

2RP-924