1625 N. French Dr., Hobbs, NM 88240 District III

1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 March 12, 2004

For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes No Type of action: Registration of a pit or below-grade tank Closure of a pit or below-grade tank

Operator: Marbob Energy Corporation	Telephone: 505-748-3303 e-ma	ail address: land2@marbob.com
Address: PO Box 227, Artesia, NM 88211-0227		
Facility or well name: Willow State No. 2 API	#: 30-015-33399 U/L or Qtr/Qtr SW	SE Sec 3 T 25S R 28E
County: Eddy Latitude Longitude	NAD: 1927 🗌 1983 🗎 Surface O	wner Federal 🔲 State 🔀 Private 🔲 Indian 🛄
Pit Type: Drilling ☑ Production ☐ Disposal ☐ Workover ☐ Emergency ☐ Lined ☑ Unlined ☐ Liner type: Synthetic ☑ Thickness 12 mil Clay ☐ Volume bbl	Below-grade tank Volume:bbl Type of fluid: Construction material: Double-walled, with leak detection? Yes If no	RECEIVED t, explain why not. APR 0 1 2005
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) (0 points) 0 points
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) (0 points) 0 points
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points) 0 points
	Ranking Score (Total Points)	0 points
If this is a pit closure: (1) attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: onsite offsite If offsite, name of facility (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No very Yes If yes, show depth below ground surface ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan . Date: March 29, 2005		
Printed Name/Title: Gerald Herrera	Signature A. Her	acc
Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Apply Apply 5 2005 Date: Printed Name/Title Signature Signature		

Marbob Energy Corporation Attachment to OCD Form C-144


Pit or Below-Grade Tank Registration or Closure

Pit Closure

Willow State #3

330' FSL & 2570' FEL Section 3 - T25S - R28E Eddy County, New Mexico

(1) Facility diagram



(2) Disposal location:

Fluids will be disposed at an approved disposal facility.

(3) General description of remedial action:

Transfer cuttings to one side of pit. Dig deep bury pit in the cleaned side of pit. Line pit with 12 mil plastic. Add material to cuttings to stiffen.

Transfer stiffened cuttings to lines pit leaving a mound in center for drainage. Cap with 20 mil liner. Cover with three feet of cover material.

(4) Groundwater encountered:

No

(5) Soil sample:

N/A