

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Kenneth N. Andersen
Address 4001 Penbrook, Odessa, TX 79762-5917	Telephone No. 505.391.5569
Facility Name Peak View Federal Battery	Facility Type Oil and Gas
Surface Owner BLM	Mineral Owner BLM
Lease No NM 70333	

LOCATION OF RELEASE

Unit Letter P	Section 35	Township 21S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy Co.
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	---------------------------

Latitude **32.43001N** Longitude **103.84616W**

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 33 bbl (30 oil, 3 water)	Volume Recovered (23 oil, 2 water)
Source of Release Peak View Btry production treater Pressure Safety Valve	Date and Hour of Occurrence 01/31/05 0330hrs	Date and Hour of Discovery 01/31/05 0625hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gerry Guye	
By Whom? Kenneth N. Andersen	Date and Hour 01/31/05 1535hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Newly drilled & completed Peak View well # 2 unloaded csg, exceeding production treater capacity causing excess fluid & pressure to exit through the PSV. A choke valve was installed on the Peak View well # 2 csg.

Describe Area Affected and Cleanup Action Taken.*

36'X150' & 36'X135' of damp caliche production btry pad, & 1.5'X1000' of damp sandy pasture. The fluid was picked up by a vacuum truck. The spill site will be sampled & delineated, and a remediation plan will be submitted to the NMOCD for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Kenneth N Andersen	TIM GUM by MB	
Title: SHE&R Specialist	Approved by District Supervisor:	Approval Date: 3/31/05 Expiration Date: N/A
E-mail Address: ken.n.andersen@conocophillips.com	Conditions of Approval: Remediation Workplan	Attached <input type="checkbox"/>
Date: 02/03/05 Phone: 505.391.5569		

- Attach Additional Sheets If Necessary



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

ConocoPhillips Co.
4001 Penbrook
Odessa TX 79762-5917

April 1, 2005

Reference: Peak View Federal Battery

P-35-21s-30e

(Incident reference API:30-015-33737)

Operator,

This letter is in regard to a release of produced fluids that occurred at the above referenced site on 1/31/2005. A remediation work plan, dated March 3 2005, has been submitted to the NMOCD District 2 office by your agent, BBC International.

The work plan is accepted with the following stipulations:

Notify NMOCD District 2 Office 24 hours prior to commencement of remediation activities.

Notify NMOCD District 2 Office 24 hours prior to any samples obtained where analysis of such samples will be submitted to the OCD.

Confirmation samples may be required prior to closure of incident.

Upon completion of operations, submit a Final Report C-141 to the District 2 NMOCD office outlining work performed and any analytical reports as required.

Like approval by the BLM.

If I can be of assistance in this matter, my contact information is listed below.

Mike Bratcher

Mike Bratcher
NMOCD District 2
1301 W. Grand Ave
Artesia, NM 88210
(505) 748-1283 Ext. 108
(505) 626-0857
mbratcher@state.nm.us