


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised March 17, 1999  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

nMLB/1214553720

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	Devon Energy	Contact	Tracy Kidd, Production Foreman
Address	P. O. Box 250 Artesia, NM 88211	Telephone No.	575-513-0628
Facility Name	Cotton Draw 65 SWD	Facility Type	Salt Water Disposal

Surface Owner	Mineral Owner	Lease No. 042565-010
---------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
65	2	25S	31E	1980	North	1980	East	Eddy

**NATURE OF RELEASE**

Type of Release	79bbls Produced Water / 1bbls Oil	Volume of Release	80 bbls	Volume Recovered	80bbls
Source of Release	Gun barrel overflow	Date and Hour of Occurrence	4/22/12, 5:33 PM	Date and Hour of Discovery	4/22/12, 5:33 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos / BLM & Mike Bratcher / OCD			
By Whom?	Date and Hour 4/23/12, 10:30 AM				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

At the Cotton Draw 65, the fill line to the water tanks from the gun barrel plugged, causing an overflow of 79 bbls of produced water and 1 bbl oil.

Describe Area Affected and Cleanup Action Taken.\*

At the Cotton Draw 65, the fill line to the water tanks from the gun barrel plugged, causing an overflow of 79 bbls of produced water and 1 bbl oil. All was within a lined containment and all liquid was recovered. Ordered vacuum truck, steamed cleaned tanks and containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Gracie C. Bustamante		OIL CONSERVATION DIVISION	
Printed Name: Gracie C. Bustamante		Signed By: <u>Mike Bratcher</u> Approved by District Supervisor:	
Title: Admin Field Support		Approval Date: MAY 24 2012	Expiration Date: N/A
Date: Phone: (575) 746-5561		Conditions of Approval: <u>N/A</u>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2LP-1127