District I
1625 N French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

MMLB 1215037627						OPERA:	ΓOR					
Name of Company Apache Corporation 373					3	Contact Natalie Gladden						
Address PO Box 1849 Eunice, NM 88231						Telephone No. 575-390-4186						
Facility Name Redlake 36 Battery (nearest well #1)						Facility Type Production Facility						
Surface Owner Mineral Owner						State of NM			API No. 30-015-33581			
				LOCA	OITA	N OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/W	est Line	County		
С	36	17S	27E	990'	FNL		2130'	FWL		Eddy		
			La	titude		Longitud	le					
				NAT	TIRE	OF RELI						
Type of Rele	ase Produc	ed water /Oil	Volume of Release 15bbls Volume Recovered 14bbls									
Source of Release Gasket Failure on Firetube							lour of Occurrence	e	Date and Hour of Discovery 3/21/12			
Was Immediate Notice Given?						If YES, To Whom?						····
		<u></u>	No □ Not Re									
By Whom? Was a Watercourse Reached?						Date and Hour						
Was a Watero	course Reac		Y No	If YES, Volume Impacting the Watercourse.								
If a Watercou	rse was Im	pacted, Descri	ibe Fully.*	:	- '	<u> </u>		-0000				· · · · · · · · · · · · · · · · · · ·
			-									
								~				
									RECEIVED			
Describe Cause of Problem and Remedial Action Taken.* Gasket failure on the firetube caused fluid to be released. All fluid remained inside the bermed area.								APR 3 0 2012				
Capital land on the freque ended find to be released. All finds femalited finding the Defined alea.									1			
									NMOCD ARTESIA			
Describe Area												
Contamination	n will be ha	nd excavated	and the N	MOCD Guideline	s will b	e followed to	closure.					
11	Salvas alva i	- C		•	-4- 4- 41	1				- ND 40	<u> </u>	
regulations all	y that the if operators a	are required to	ven above report an	is true and comple d/or file certain re	ete to ti lease n	ne best of my a otifications an	knowledge and ur d perform correct	nderstand tive action	that pursurs	uant to NMO ases which n	CD n	ules and ndanger
public health of	or the envir	onment. The	acceptance	e of a C-141 repor	t by the	NMOCD ma	rked as "Final Re	port" doe	s not relie	eve the opera	tor of	fliability
or the environ	perations ha ment In ad	ave tailed to action NMO	dequately CD accent	investigate and re ance of a C-141 re	mediate enort de	e contaminationes not relieve	on that pose a thre	at to grou	ind water,	surface water	r, hu	man health
federal, state,							- the operator of it			miphanee wii	a	
Signature: Dui Joddu						OIL CONSERVATION DIVISION						
												Approved by Environmental Specialist:
						Printed Name:	Natalie Gl	ladden				
Title: EHS Environmental Tech						Approval Date: Expiration Date:						
E-mail Addres	s: natalie o	ladden@anac	hecom co	m		Conditions of	Approval:					
E-mail Address: natalie.gladden@apachecorp.com						Conditions of Approval: Remediation per OCD Rules &				Attached		
Date: 3/23/12 Phone: 575-390-4186						LIGHT REIVIEDIATION						
Attach Additional Sheets If Necessary						DODOSAL NOT LAIER ITIOIT				aRA	1	1/33
					PKC	6/29	12012			ひ)	/	1 2 2
							1					