

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nMLB 1216757185

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report	
Name of Company BOPCO, L.P. <i>260737</i>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name James Ranch Unit 29 SWD	Facility Type E&P

Surface Owner State of New Mexico:	Mineral Owner State of New Mexico	Lease No. <i>APZ *</i>
------------------------------------	-----------------------------------	------------------------

LOCATION OF RELEASE

Unit Letter K	Section 36	Township 22S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.346284 Longitude W 103.837459

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 175 Bbls of Produced water	Volume Recovered: 50 Bbls
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence 5/22/12 Time unknown	Date and Hour of Discovery 5/22/12 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104	
By Whom? Tony Savoie	Date and Hour 5/22/12 2:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.* The flow line developed a leak due to internal corrosion. The SWD pump at the JRU-29 was shut down and 1 joint of pipe was replaced.

Describe Area Affected and Cleanup Action Taken.* Approximately 3240 sq. ft. of pasture land. All of the free standing water was picked up with a vacuum truck. The spill stayed within the pipeline right-of-way. A backhoe was used to collect samples at the point of release and the ponded areas on 5/30/12 to determine the vertical and horizontal extent. The remediation will comply with the NMOCD and BLM requirements for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by District Supervisor <i>[Signature]</i>	
Title: Waste Mgmt. & Remediation Specialist		Approval Date: JUN 15 2012	Expiration Date:
E-mail Address: TASavoie@BassPet.com		Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 7/15/2012	
Date: 6/3/12 Phone: 432-556-8730		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary



2RA-1174