

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

0JMW 1217332607 OPERATOR X Initial Report Final Report

Name of Company	Read & Stevens, Inc	Contact	Will Palmer
Address	PO Box 1719, Lovington, NM 88260	Telephone No.	(575) 396-5391
Facility Name	Marbob State Tank Battery	Facility Type	tank battery

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	Lease No.	API 30-015-37930
---------------	---------------------	---------------	---------------------	-----------	------------------

LOCATION OF RELEASE

Marbob State #3

Unit Letter	Section 19	Township 19-S	Range 29-E	Feet from the 660'	North/South Line North	Feet from the 1980'	East/West Line East	County Eddy
-------------	---------------	------------------	---------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	produced oil	Volume of Release	~300 bbls	Volume Recovered	210 bbls
Source of Release	Tank bottom developed leak	Date and Hour of Occurrence	Between 0800 hours 6.10.12 and 0800 hours 6.11.12	Date and Hour of Discovery	06.11.12 0800 hours
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Mike Bratcher, OCD		
By Whom?	Mr. Will Palmer	Date and Hour	06.11.12 - 1000 hours		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

JUN 18 2012

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

bottom of oil storage tank developed a leak. Tank to be repaired and recoated.

Describe Area Affected and Cleanup Action Taken.*

The affected area is contained in a 50' x 25' decreasing to 3' wedge shaped tract outside bermed area. The affected soil is being removed and taken to an OCD approved land farm. Surface soil samples will be taken and checked for hydrocarbon contamination. Fresh topsoil will be contoured over the area. Earthen berms will be re-built and liner re-installed around the tank battery.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>William V. Palmer</u>	OIL CONSERVATION DIVISION	
Printed Name: William V. Palmer	Approved by District Supervisor:	Signed By: <u>Mike Bratcher</u>
Title: Manager, Production & Completions	Approval Date: <u>JUN 21 2012</u>	Expiration Date:
E-mail Address: <u>WPALMER@READ-STEVEN.S.COM</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 15, 2012 Phone: 505.396.5391		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

7/21/12

2 RP-1179