


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW 1219 439 454
Name of Company: Linn Operating 269324
Address: 2130 W. Bender Hobbs, NM 88240
Facility Name: HE West A 28
OPERATOR
Contact: Joe Hernandez
Telephone No.: 575-738-1739
Facility Type: Oil
☒ Initial Report ☐ Final Report

Surface Owner: Federal Mineral Owner: Federal API No.: 3001528318

LOCATION OF RELEASE

Unit Letter H	Section 03	Township 17S	Range 31E	Feet from the 1980	North/South Line North	Feet from the 505	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.86533 Longitude: -103.84987

NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 2 / 3	Volume Recovered: 0 / 0
Source of Release: Polyline	Date and Hour of Occurrence: 06/21/2012 2pm	Date and Hour of Discovery: 06/21/2012 2:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher -NM OCD / Terry Gregston- BLM	
By Whom? Joe Hernandez	Date and Hour 06/22/2012 4pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Pumper was checking wells. Spotted a 3" poly leaking out in pasture, put pipe clamp and shut in well.

Describe Area Affected and Cleanup Action Taken.* : In the pasture , leak on north side of road. Further remedial action pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Approved by District Supervisor: Signed By	
Title: Production Foreman	Approval Date: JUL 12 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/02/2012 Phone: 575-942-9492		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8/12/12

2RP-1216