

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis
Santa Fe, NM 87505

17 2012 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

NMOCD ARTESIA

Release Notification and Corrective Action

Name of Company: BOPCO, L.P. 260737		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Tony Savoie	Telephone No. 432-556-8730	
Facility Name: James Ranch Unit #73		Facility Type: Pumping well		
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-28979

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	6	23S	31E	330	North	1980	West	Eddy

Latitude: N 32.339866

Longitude: W 103.819202

NATURE OF RELEASE

Type of Release: Produced Water and crude oil	Volume of Release 5 bbls crude oil and 5 bbls produced water	Volume Recovered: None
Source of Release: Pumping well stuffing box packing	Date and Hour of Occurrence: 7/14/12 Time unknown	Date and Hour of Discovery: 7/14/12 Approximately 12:30 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? BLM at 9:00 a.m. 7/16/12	
By Whom? Tony Savoie	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The well was shut in and the stuffing box packing was replaced.		
Describe Area Affected and Cleanup Action Taken.* Approximately 7250 sq.ft. of caliche well pad was affected by the release, all of the fluid had soaked into the ground upon discovery; a backhoe was used to scrape up the heavily saturated soil and was stockpiled on-site. The remediation will follow the NMOCD and BLM spill guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: Signed By Mike Brannon	
Title: Waste Mgmt. and Remediation Specialist	Approval Date: AUG 01 2012	Expiration Date:	
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 7/16/12	Phone: 432-556-8730		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:

9/1/12

2RP-1235