

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1219 331428
Name of Company BOPCO, L.P. 260737 OPERATOR ☒ Initial Report ☐ Final Report
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Contact Tony Savoie
Facility Name Poker Lake Unit 213 SWD Telephone No. 432-556-8730
Facility Type E&P
Surface Owner Federal Mineral Owner Federal Lease No. NMNM-02860-APC

LOCATION OF RELEASE

30-015-33859
Unit Letter P Section 30 18 Township 24S Range 30E Feet from the North/South Line Feet from the East/West Line County Eddy

Latitude N 32.212505 Longitude W 103.914199

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 5 Bbls of Produced water and 5 Bbls crude oil	Volume Recovered: None
Source of Release: Tank Overflow	Date and Hour of Occurrence 5/28/12 Time unknown	Date and Hour of Discovery 5/28/12 10:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM	
By Whom? Tony Savoie	Date and Hour 5/29/12 8:55 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The SWD tanks overflowed due to a pump malfunction and high level alarm failure. The water coming into the facility was diverted and the power was restored to the facility the next day

Describe Area Affected and Cleanup Action Taken.* The SWD tanks are inside a poly lined metal containment which contained most of the released fluid, the wind was blowing extremely hard to the north west carrying the fluid outside of the containment and misting an area of approximately 23,400 sq. ft of pasture land with a fine mist of oil and water. The soil had less than 1/4" of saturation. The area around the pumps and concrete pad area were affected by the release with a saturation of approximately 1 ft. in depth. The remediation will comply with the NMOCD and BLM requirements for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor:	
Title: Waste Mgmt. & Remediation Specialist	Signed By: [Signature] Approval Date: JUL 11 2012 Expiration Date:	
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/22/12 Phone: 432-556-8730		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8/11/2012

