

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

MLB/22403573

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company-Cimarex Energy	Contact- James Tinney
Address-600 N Marienfeld Ste 600, Midland Tx 79701	Telephone No. 575 706 0095
Facility Name-Mayaro 22 state 3	Facility Type- Tank battery

Surface Owner	Mineral Owner	Lease No.30-015-38323
---------------	---------------	-----------------------

LOCATION OF RELEASE

Unit Letter I	Section 22	Township 17S	Range 28E	Feet from the 1820	North/South Line FSL	Feet from the 330	East/West Line FEL	County - Eddy
-------------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude- _____ Longitude- _____

NATURE OF RELEASE

Type of Release- oil to flare	Volume of Release-	Volume Recovered-
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD left message 7/19/12 8:23A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
JUL 20 2012
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Take Oil dump failed send a small amount of oil to flare on location causing a small fire at the base of the flare, was contained at the flare. Corrected problem with dump valve. Inspected flare for damage. Fluid on ground was less than 1 bbl

Describe Area Affected and Cleanup Action Take Area at base of flare, top soil(caliche) was burnt around flare, will clean up when flare is removed
--

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>James Tinney</u>		OIL CONSERVATION DIVISION	
Printed Name: James Tinney		Approved by District Supervisor: <u>Mike Bratcher</u>	
Title: Assistant Production Foreman		Approval Date: AUG 27 2012	Expiration Date:
E-mail Address: jtinney@cimarex.com		Conditions of Approval:	
Date: 7-20-12 Phone: 575-706-0095		Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

9/27/12

2RA-1237