Submit One Copy To Appropriate District Office	ice State of New Mexico		Form C-103 Revised August 1, 2011	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, witherars and inatural	WELL A		
District II 811 S. First St., Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	OIL CONSERVATION DI 1220 South St. Francis Santa Fe, NM 8750	Dr. S. Indic	ate Type of Lease TATE FEE X Oil & Gas Lease No.	
1220 S. St. Francis Dr , Santa Fe, NM 87505				
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA"			e Name or Unit Agreement Name E FARMS	
PROPOSALS.) 1. Type of Well: XOil Well Gas Well Other		8. Well	•	
2. Name of Operator Chesapeake Operating, Inc.		9. OGR	ID Number 147179	
3. Address of Operator P.O. Box 18496 Oklahoma City, OK 73154			l name or Wildcat G; DELAWARE, EAST	
4. Well Location RECEIVED				
Unit Letter A : 660' feet from the North line and 660' feet from the East line				
Section 10 Township 23 S Range 28 E NMPM County ED 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			3L1 V 0 2U12	
2998' GR NMOCD ARTESIA				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
TEMPORARILY ABANDON 🔲	PLUG AND ABANDON RECHANGE PLANS CO	SUBSEQUE EMEDIAL WORK DMMENCE DRILLING OP ASING/CEMENT JOB	NT REPORT OF: ALTERING CASING NS. P AND A	
OTHER:				
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
In the location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.				
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
	have been addressed as per OCD rule a abandoned in accordance with 19.15		s have been removed from non-	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE Day has	TITLE Regula	ntory Specialist II	DATE <u>09/05/2012</u>	
TYPE OR PRINT NAME Bryan Arran	,	van.arrant@chk.com	PHONE: <u>(405)935-3782</u>	
APPROVED BY Conditions of Approval (if any):	TITLE OF	to Release	DATE 9/10/2012	