<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1000 Rko Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

AUG 3 0 2012 Form C-141 Reviser October 10, 2003

NMOCD Afforms Portes to appropriate with Rule 116 on back side of form

Notification		

n5mW1225639143						OPERATOR			Initia	al Report		Final Report
Name of Company Oxy Permian Ltd. 192463:						Contact Christopher Jones						
Address 1502 W. Commerce Dr., Carlsbad, NM						Telephone l		4121				
Facility Name Smokey Bits State Com #5H Fac							e '	•••			***************************************	
Surface Owner State Mineral Owner									Lease No. API#30-015-40070			
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	North	South Line	Feet from the	East/West Line		County		
M	36	185	30E	330'		S	330		W Eddy County, NM			1
Latitude N 32.69781° Longitude W 103.93297°												
NATURE OF RELEASE												
Type of Release Oil and Produced water Volume of Release 15 bbls oil, Volume Recovered 100 bbls												
Source of Re	leace Vice	e tank bottom	falloss			95 bbls produced water Date and Hour of Occurrence Date and Hour of Discovery						
Source of K	lease Pla	c and conom	Täntific			8/14/12	out or occurrence	Date and Hour of Discover 8/14/12			LOVELY	ĺ
Was Immedi	ate Notice C					If YES, To						
		i X	Yes L	No Not Re	quired	Mike Bran	her- OCD					ļ
By Whom?	Christoph					Date and Hour 8/14/12 @ 12:24 pm						
Was a Water	course Reac	thed?	Yes 🛭	No		If YES, Vo	lume Impacting th	he Wate	rcourse.			
				·	······································	<u></u>			· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·		
II a waterco	urse was im	pacted, Descri	ice ruity.	•								
										1		
Describe Car	use of Proble	m and Reme	dial Action	Taken.*					· · · · · · · · · · · · · · · · · · ·			
Failure of a f	rac tank bot			il and 95 bbls of p	oduced	d water to lead	onto the ground.	100 bi	ols of produ	iced water w	ere reco	overed via
vacuum truck	<b>C.</b>											ł
Describe Are	a Affected a	ind Cleanup A	Action Tak	en.*	<del></del>				<del></del>			
Failure of a	frac tank bot	tom caused I	5 bbls of c	il and 95 bbls of p				. 90 ъь	ls of produ	ced water we	are teco.	vered via
vacuum truck. Remediation will be performed in accordance with an OCD-approved remediation plan.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations.												
								OIL CONSERVATION DIVISION				
Signature:	A.										1.1	<i>i</i> /
Printed Name	: Christon	oher Jones			1	Approved by 1	District Supervisor	r:	Signed	By M	1/4/	Bemour
	Specialist					Approval Date	: SEP 1	2 2	A12tion L			
	Mark J. William			· · · · · · · · · · · · · · · · · · ·				<u> </u>	estador L			
E-mail Addre	ss: Christ	opher Jones@	ېزoxy.com			Conditions of	Approval:			Attached		
Date: 8	30-12		Phone:	(575) 628-4121							manud	
Attach Addit			(0.0) 300 1101	tion per OCD	Rules	&	2.5	-Q	1285			

**Guidelines. SUBMIT REMEDIATION**