District I 1625 N. French Dr., Hobbs, NM 88240 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

mMLB/226546393

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED SEP 05 2012

Form C-141 Revised October 10, 2003

NMOCD ARTEMA opies to appropriate office in accordance with Rule 116 on back

side of form

## Release Notification and Corrective Action

**OPERATOR** 

Name of Company COG OPERATING LLC 229/37						Contact Pat Ellis				
Address 550 W. Texas, Suite 100, Midland, TX 79701						Telephone No. 432-230-0077				
Facility Name Honey Graham State Com #1H Tank Battery Facil							Facility Type Tank Battery			
Surface Owner State Mineral Owner								Lease N	lo. (API#) 30-015-37465	
LOCATION OF RELEASE										
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	East/West Line	County	
D	29	26S	28E						Eddy	
		_								
Latitude 32 01.204 Longitude 104 06.974										
NATURE OF RELEASE										
Type of Release Produced water							Volume of Release 90bbls   Volume Recovered 89bbls     Date and Hour of Occurrence   Date and Hour of Discovery			
Source of Release Water tank						08/20/2012			Date and Hour of Discovery	
Was Immediate Notice Given?						08/20/2012				
Yes No Not Required Mike Bratcher-OCD										
By Whom? Josh Russo						Date and Hour 08/21/2012 1:35 p.m.				
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.			
☐ Yes ☒ No										
If a Watercourse was Impacted, Describe Fully.*										
Describe Cause of Problem and Remedial Action Taken.*										
A water transfer pump failed which allowed for the produced water tank to fill and overflow into the facility. We are installing an alarm at this facility to prevent reoccurrence.										
Describe Area Affected and Cleanup Action Taken.*										
Initially 90bbls of produced water were released from the water tank and we were able to recover 89bbls with a vacuum truck. All released fluid was contained inside the lined facility walls of the tank battery. We have recovered all standing fluid and disposed of all contaminated gravel. We have added										
								posed of all contain	inated gravei. We have added	
fresh gravel to the facility as necessary. This facility has been returned to its prior condition.										
I hereby certif	y that the in	nformation give	en above	is true and comp	ete to t	he best of my	knowledge and ur	derstand that purs	uant to NMOCD rules and	
									ases which may endanger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability										
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health										
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.										
rederal, state,	or rocar raw	rs and or regu	400113.		T		OIL CONS	SERVATION	DIVISION	
Signature:										
A						Approved by District Broad Broad Semana				
Time traine. Josi Russo										
Title:		HSE Co	ordinator			Approval Dat	SEP 2 1 20	Expiration I	Date: H/A	
E-mail Address: jrusso@conchoresources.com Conditions of Approval:										
IIIaii /IddiCa		ji usso(u;conci	ioi caoui C	vo.vviii		Conditions of Approval: Attached				
Date: 09/05	/2012	Phone:	432-2	12-2399				NH		
Attach Additi	onal Shee	ts If Necessa	ry						201 1200	
								0	(KN-127]	