Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

OCD Artesia

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

	orm for proposals to drill or Jse Form 3160-3 (APD) for s				
SUBMIT	IN TRIPLICATE – Other instructions	7. If Unit of CA/Agree NM126412X	7. If Unit of CA/Agreement, Name and/or No. NM126412X		
Oil Well Gas Well Other				8. Well Name and No. Benson Delaware Unit #2	
2. Name of Operator CHI Operating, Inc.			9. API Well No. 30-015-31778	9. API Well No. 30-015-31778	
3a. Address P.O. Box 1799 Midland, TX 79702	lo. (include area code) 001	10. Field and Pool or Exploratory Area Benson Delaware Unit			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) M-1-19S-30E 990' FSL & 660' FWL			11. Country or Parish, Eddy Co., NM	11. Country or Parish, State Eddy Co., NM	
12. CHEC	K THE APPROPRIATE BOX(ES) TO IN	NDICATE NATURE OF N	OTICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION TYPE OF ACTION					
Notice of Intent	Alter Casing Fra	eepen	Production (Start/Resume) Reclamation Recomplete	☐ Water Shut-Off ☐ Well Integrity ☐ Other	
, Subsequent Report		ug and Abandon	Temporarily Abandon	Other	
Final Abandonment Notice	Convert to Injection	ug Back	Water Disposal		
testing has been completed. Final determined that the site is ready for 5/15/12 NDWH, NUBOP LD SN and w/165 jts, cleaned dwn to 5243, POPU 113 jts IPC pipe, set pkr @ 3695 good, pumped out plug from pkr with CAY NI ARBURGO RY SEE SEE	d perf sub, PU notch collar, flappers, r. DH and LD jts, LD sand bailer, flappers, r. Circ 110 bbls pkr fluid, latched back of 600ps. Close well in, shut down. NOCO - PACKAN WEX - 897 ID 1912 ATTACHED Conditions of	after all requirements, incl ran 14 jts, PU sand baile r valves and notch collar	or and drain nipple, RIH w/r. PU pkr (Arrow set 1X-2 and well up. Press test the DIBLM OFFAL UCLEAR ACCEPTE	remaining tbg, tgged @ 5203 7/8 x 5 1/2 with 2.25 profile nipple. pkr @ 500 psi for 30 min, held NTOLVAL AS DES NOT HAVE AUTH OF OR RECORD ON S DEC 10 2012	
14. I hereby certify that the foregoing is t	rue and correct. Name (Printed/Typed)		1 10	ALL OF LAND NIAN OFFICE	
PAM CORBETT pamc@chienergy	Title Regulatory Cl	erk BORE	AU OF LAND MANAGEMENT ARISBAD FIELD OFFICE		
Signature Tarv	Cabit	Date 04/12/2011		·	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by Conditions of approval, if any, are attached that the applicant holds legal or equitable entitle the applicant to conduct operations			Date		
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a crime for an	v person knowingly and wil	Ifully to make to any departme	nt or agency of the United States any false.	

Order of Authorized Officer

And

Conditions of Acceptance of Sundry Subsequent Report dated 04/12/2011

Chi Operating, LLC Benson Delaware Unit - 02 API 3001531778, T19S-R30E, Sec 01 December 10, 2012

- 1. Although this **Federal well** is within the boundaries of the Benson Delaware Unit as described by NMOCD order R-13262, it is not listed as one of the nine listed injection wells.
- 2. Federal Regulation 43CFR 3162.3-2 Subsequent Well Operations requires Bureau of Land Management approval for conversion to injection. This well lacks that approval and is out of compliance, a Notice of Intent Sundry should have been submitted prior to the conversion.
- 3. The subsequent sundry (04/12/2011) indicates the injection packer was set at 3695'. The reported top perforation is 5082'. Move the packer within 100ft of the uppermost injection perforations or casing shoe as indicated by Order R-13262.
- 4. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 4400 or below to top of cement. The CBL may be attached to a pswartz@blm.gov email.
- 5. Available records do not indicate the setting depth of the 5 $\frac{1}{2}$ " DV Tool. Report that depth.
- 6. Perform a BLM PET witnessed (charted) casing integrity test of 900 psig. Pressure leakoff may require correction for approval. Include a copy of the chart in the subsequent sundry.
- 7. The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity.
- 8. Contact the Authorized Officer: Paul R. Swartz <u>pswartz@blm.gov</u> phone 575-200-7902 to ensure that the following requirements are met and other questions.
- **9.** Submit the BLM Form 3160-**4 Recompletion Report** within 30 days of the date all BLM approved procedures are complete.
- **10.** See additional requirements below "<u>Well with a Packer Operations"</u> contact Swartz <u>pswartz@blm.gov</u> phone 575-200-7902 for further explanation.

EGF 121012

Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal any time more than five barrels of packer fluid is replaced within 30 days.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with 200 psig differentials between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- 4) At least 24 hours before the test: email Paul R. Swartz <u>pswartz@blm.gov</u> phone 575-200-7902. Note the contact notification method, time, & date in your subsequent report.
- 5) Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 6) Use of tubing internal protection, tubing on/off equipment and a profile nipple just above the packer are required injection equipment. The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.
- 7) Submit the original subsequent sundry with three copies to BLM Carlsbad.
- 8) Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization.
 - a) Approved injection pressure compliance is required.
 - b) If injection pressure exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.
 - c) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 9) Unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- 10) The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 11) Maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is required.

- 12) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 13) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 14) Gain of annular fluid requires notification within 24 hours. Cease injection and maintain a production casing pressure of 0psia. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov</u>>, cell phone 575-200-7902). If there is no response phone 575-361-2822.
- 15) Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of equipment: internally corrosive protected tubing, profile nipple, and tubing on/off equipment just above the packer. The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil and gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.