

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
OCT 29 2012
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW 1231150890

OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	High Net Federal SWD	Facility Type	SWD

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-35602
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
2	2	25S	28E					Eddy

Latitude 32.1162 Longitude 104.0563

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	15bbls	Volume Recovered	12bbls
Source of Release	Gun barrel tank	Date and Hour of Occurrence	10/10/2012	Date and Hour of Discovery	10/10/2012 3:00 p.m.

Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?
-----------------------------	--	------------------

By Whom?	Date and Hour
----------	---------------



Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.
----------------------------	---	---

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The gun barrel tank overflowed at the SWD facility due to the fact that the alarm has not been installed yet. Alarms will be installed on the oil tanks to prevent re-occurrence.

Describe Area Affected and Cleanup Action Taken.*
Initially 15bbls were released from the overflowed gun barrel and we were able to recover 12bbls with a vacuum truck. The fluid ran into the lined facility and was contained by the dike walls. All free fluid has been recovered and the contaminated gravel has been removed. The tanks and the liner have been steam cleaned and fresh gravel has been replaced into the SWD. The facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By 
Title:	Senior Environmental Coordinator	Approval Date:	NOV 06 2012
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	10/25/2012	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

Dec. 6, 2012

2RP-1390

Closed 1/22/13 MB