


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1301552456
Name of Company Oxy Permian Ltd. 192463
Address 1502 W. Commerce Dr., Carlsbad, NM
Facility Name Righthand Canyon 35-7 SWD
Contact Christopher Jones
Telephone No. (575) 628-4121
Facility Type SWD
Surface Owner Mineral Owner Lease No. API#30-015-34529

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	21S	24E	1975	South	2405	West	Eddy County, NM

Latitude Longitude

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 175 bbls	Volume Recovered 0 bbls
Source of Release Failure in 2" valve on the discharge line	Date and Hour of Occurrence 12/27/2012	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- OCD, James Amos-BLM. Terry Gregston-BLM	
By Whom? Christopher Jones	Date and Hour 12/27/2012 @ 1:53 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Failure in a 2" valve on the discharge line caused 175 bbls of produce water to leak onto the ground. Fluids were not recoverable. The valve was repaired.

Describe Area Affected and Cleanup Action Taken.*

Failure in a 2" valve on the discharge line caused 175 bbls of produce water to leak onto the ground. Fluids were not recoverable. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: [Signature]
Printed Name: Christopher Jones
Title: HES Specialist
E-mail Address: Christopher.Jones@oxy.com
Date: 1-3-13 Phone: (575) 628-4121
OIL CONSERVATION DIVISION
Approved by District Supervisor: Signed By [Signature]
Approval Date: JAN 15 2013 Expiration Date:
Conditions of Approval: Attached ☐

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
February 15, 2013

2RP-1493