Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office SECENTED Windows and Network Description	Revised November 3, 2011
1625 N Franch Dr. Libbb. 81M 88240	WELL API NO.
District II 811 S. First St., Artesia, NM 882F0B 13 2013 OIL CONSERVATION DIVISION	30-015-23070
	5. Indicate Type of Lease STATE FEE
District IV District IV ARTESIA 220 South St. Francis Dr. Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Delhi State
PROPOSALS.) 1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other	8. Well Number 5
2. Name of Operator	9. OGRID Number
COG Operating LLC	229137
3. Address of Operator One Concho Center, 600 W. Illinois Avenue, Midland, TX 79701	10. Pool name or Wildcat Artesia; Queen-Grayburg-San Andres
4. Well Location	Tatesia, Queen Graybarg San Tinares
Unit Letter <u>D</u> : <u>330</u> feet from the <u>North</u> line and 330 feet from the <u>West</u> line	
Section 33 Township 17S Range 28E NMPM County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3684' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
	ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB
OTHER:	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT	
LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY	
STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to so	nedule an inspection.
SIGNATURE	
SIGNATURE TITLE Regulatory Analyst	DATE2/11/13
TYPE OR PRINT NAME Brian Maiorino E-MAIL: bmaiorino@conch	o.comPHONE: _432-221-0467
For State Use Only	
APPROVED BY INNO. Sum TITLE C.O. OK. TO RELEASE.	DATE 3/8/13
OK. TO RELEASE.	