District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 2040 South Pacheco Santa Fe, NM 87505 Form C-141 Revised March 17, 1999

Final Report

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Initial Report

nMLB 0527748654

Release Notification and Corrective Action OPERATOR

Name of Company Clayton Williams Energy, Inc.							Contact□ Matt Swierc, Production Supt.					
Address Six Desta Drive, #3000, Midland, TX 79705							Telephone No. ☐ (432) 682-6324					
Facility Name Jenna Com (Property 25679)							Facility Type□ SWD Battery/System					
[C C C	04-4-	-CN N/		1 365	Carte CN - Marie							
Surface Owner State of New Mexico Mineral Owner							State of New Mexico Lease No.					
LOCATION OF RELEASE												
Unit Letter	Section	Township	Feet from the				est Line County Eddy					
1	5	17S	Range 29E	2210	south		990	East		County	-J	
7												
NATURE OF RELEASE												
Type of Release produced salt water							Volume of Release 28 bbl. wtr Volume Recovered □ 25 bbls					
Source of Release pump							Date and Hour of Occurrence 07-29- Date and Hour of Disc				overy 7-	
							05, 7 am 29-05, 10 am					
Was Immediate Notice Given?						If YES, To Whom?						
✓ Yes No Not Required						Mr. Mike Bratcher						
By Whom? Butch Reid, Contract Pumper Was a Wassesser Bushed?						Date and Hour 7/29/05, 12 noon						
Was a Watercourse Reached? Yes No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*												
Pressure fitting broke on end of pump releasing 25-30 bbls. produced water inside dike.												
Describe Area Affected and Cleanup Action Taken.*												
					ed up 25	bbls. water					i	
Affected Area: Spill contained inside dike area. Vacuum truck picked up 25 bbls. water												
The boundaries and the second of the second												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may												
endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator												
of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface												
water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for												
compliance wit	h any other	federal, state,	or local l	aws and/or regula	tions.			-				
							OIL CONSE	RVATI	ON DI	VISION	7	
Signature: Betsy Luna							TIM GUM					
Printed Name:	Retev I n	U /		[-	Approved by District Supervisor: by MB							
I IIIICU INMIIC:	Detay Lu	<u> </u>						7			7400	
Title: Engineering Technician						Approval Date: 10/4/55 Expiration Date:						
	<u>-</u>								4		X	
Date:		P	hone: (4	32) 682-6324	- 1	Conditions o	f Approval:			Attached	ן אַז	
* Attach Addi	. 1.01						· · · · · · · · · · · · · · · · · · ·			· 		



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

Clayton Williams Energy, Inc. Six Desta Drive, #3000 Midland TX 79705 October 4, 2005

Reference: Jenna Com SWD

I-5-17s-29e

30-015-29260

Incident Number: nMLB0527748654

Operator,

A borehole sampling/delineation work plan has been submitted by your agent, Highlander Environmental Services for delineation of contaminants at the above referenced well site.

The work plan is accepted as presented with the following stipulations:

NMOCD may alter work plan as site conditions warrant.

Contact NMOCD District 2 office 24 hours prior to commencement of operations.

Contact NMOCD District 2 office 24 hours prior to obtaining samples where analysis of such samples are to be submitted to the NMOCD.

Please submit a "Final Report" C-141 upon completion of project.

Please be advised that acceptance of documents and/or work plan does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

Please commence operations no later than November 4, 2005.

If I can be of assistance in this matter, my contact information is listed below.

Thank you,

Mike Bratcher NMOCD District 2

1301 W Grand Ave

Artesia, NM 88210 (505) 748-1283

(505) 626-0857

Mike.Bratcher@state.nm.us