Submit 1 Copy To Appropriate District OfficeState of New MexicoDistrict I - (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410State of New Mexico Energy, Minerals and Natural ResourcesOIL CONSERVATION DIVISION 1220 South St. Francis Dr. Sonto Fo. NM 87505	Form C-103 Revised August 1, 2011 WELL API NO. 30-015-01497 5. Indicate Type of Lease STATE X FEE
District IV         - (505) 476-3460         Santa Fe, NM 87505           1220 S. St. Francis Dr., Santa Fe, NM         87505	6. State Oil & Gas Lease No. B-1969
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	<ol> <li>Lease Name or Unit Agreement Name GULF STATE</li> </ol>
1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other	8. Well Number 002
2. Name of Operator TANDEM ENERGY CORPORATION	9. OGRID Number 236183
3. Address of Operator 2700 Post Oak Blvd. Ste 1000 Houston, Texas 77056	10. Pool name or Wildcat Red Lake Queen Grayburg San Andres
4. Well Location       Unit Letter       C       : 330 feet from the N       line and 2310 feet from the W       line         Section       22       Township       17S       Range       28E       NMPM       County       EDDY         11. Elevation (Show whether DR, RKB, RT, GR, etc.)       3550' GR       3550' GR       11.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:       SUBSEQUENT REPORT OF:         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK       ALTERING CASING         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OPNS.       P AND A         PULL OR ALTER CASING       MULTIPLE COMPL       CASING/CEMENT JOB       CASING/CEMENT JOB	
OTHER:       OTHER:       Image: Complete completions.       OTHER:       Image: Complete completions.         13. Describe proposed or complete	
Rigged up pulling unit to repair tubing leak. Pulled out of the hole with rods, pump and tubing. Pressure tested tubing in the hole replacing the joints that did not hold pressure. Ran in hole with pump and rods. Spaced out pump. Hung well on. Restored well to production, January, 2013.	
NOTE: Since a notice of intent was not filed before the work was done, Daniel Sanchez with Enforcement in Santa Fe said to file a subsequent report.	
APR 09 2013 NMOCD ARTES:A	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Rusty anold TITLE Production Engineer DATE 4/8/2013	
Type or print name Rusty Arnold E-mail address: rarnold@plater	
APPROVED BY: Roade TITLE Dist B Spen DATE 4/4/13	
Conditions of Approval (if any):	