


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*njmw* 131015645 OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	YUCCA STATE (Willow State)	Facility Type	TANK BATTERY
Surface Owner	STATE	Mineral Owner	
		Lease No. (API#) 30-015-28880	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	16	17S	31E					EDDY

Latitude 32.82822 Longitude 103.87359

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	9bbbls	Volume Recovered	8bbbls
Source of Release	1/2" valve on header	Date and Hour of Occurrence	03-23-2013	Date and Hour of Discovery	03-23-2013 11:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
1/2" valve on header was partially open. Closed valve to prevent further release of fluids.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 9bbbls were released from a 1/2" partially opened valve on the header we were able to recover 8bbbls with a vacuum truck. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed from the facility. Fresh gravel has been added as necessary. The facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:					
Printed Name:	Josh Russo				
Title:	Senior Environmental Coordinator				
E-mail Address:	jrusso@concho.com				
Date:	04-03-2013	Phone:	432-212-2399		
			<b>OIL CONSERVATION DIVISION</b>		
			Accepted for record NMOCD		
			Approved by District Supervisor:		
			Approval Date:		Expiration Date:
			Conditions of Approval:		Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-1615

Accepted for record  
NMOCD