

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
MAR 26 2013
Submit 1 Copy to appropriate District Office in NMOCD ARTESIA

Form C-141
Revised August 8, 2011
District Office in
9.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1309930190 OPERATOR Initial Report Final Report

Name of Company Apache Corporation 873	Contact Natalie Gladden
Address PO Box 1849, Eunice NM 88231	Telephone No. 575-390-4186
Facility Name Tony Federal Battery (nearest well #1)	Facility Type Production Facility
Surface Owner BLM	Mineral Owner BLM
API No. 30-015-30244	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	18	17S	31E	1385'	FSL	1410'	FWL	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15	Volume Recovered 5
Source of Release Hole in 4" check valve	Date and Hour of Occurrence 05/23/12	Date and Hour of Discovery Same
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Amos/Bratcher	
By Whom? Natalie Gladden	Date and Hour 05/23/12	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Pin hole size leak in the body of the 4" check valve on the water transfer line.

Describe Area Affected and Cleanup Action Taken.*
Site will be remediated by NMOCD/BLM Guidelines to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by Environmental Specialist: Signed By <i>Natalie Gladden</i>	
Title: Sr. Environmental Tech	Approval Date: APR 08 2013	Expiration Date:
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 5/26/12 Phone: 575-390-4186	PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

May 9, 2013
2RP-1605