

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
MAR 15 2013  
NMOC D ARTESIA

Form C-141  
Revised March 17, 1999  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*DJM* 1308635962 OPERATOR  Initial Report  Final Report

Name of Company Devon Energy	Contact Daniel Suniga, Production Foreman
Address P. O. Box 250 Artesia, NM 88211	Telephone No. 575-390-5850
Facility Name Todd 15B Federal #2	Facility Type Oil Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	15	23S	31E	660	North	1980	East	Eddy County

*\*API 30-015-33104*

**NATURE OF RELEASE**

Type of Release Spill	Volume of Release 20pw / 3 oil	Volume Recovered 15pw / 1 oil
Source of Release Poly line Leak	Date and Hour of Occurrence 03/11/13, 10:00 AM	Date and Hour of Discovery 03/11/13, 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos/ BLM, Mike Bratcher, OCD	
By Whom? Daniel Suniga	Date and Hour 3/11/13, 11:00 am, 03/12/13, 10:15 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
At the Todd 15B Federal #2, the contract inspector was gathering coordinates for a water transfer line, when he discovered a leak of 23bbls of mixed fluid coming from the 4" poly line.

Describe Area Affected and Cleanup Action Taken.\*  
At the Todd 15B Federal #2, the contract inspector was gathering coordinates for a water transfer line, when he discovered a leak of 23bbls of mixed fluid coming from the 4" poly line. The leak occurred in the middle of a pasture, releasing 20 bbls of produced water and 3 bbls of oil. The poly line was scraped when it was being unloaded off the delivery truck. Lease operator was notified and fenced off affected area, shut in the line, contacted a vacuum truck, replaced 10 feet of poly line, prepared clean up. Fluid recovered was 15 bbls of produced water and 1 bbl of oil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Graciela C. Bustamante</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Graciela C. Bustamante	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title: Field Admin Support	Approval Date: MAR 27 2013	Expiration Date:
Date: 03/12/13 Phone: (575) 746-5561	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**  
*April 27, 2013*

*2RP-1590*