


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
This form applies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JMW 1309539213 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	WAY SOUTH STATE COM #001H	Facility Type	TANK BATTERY
Surface Owner	STATE	Mineral Owner	
		Lease No. (API#) 30-015-37234	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	30	26S	28E					EDDY

Latitude 32.01862 Longitude 104.13424

NATURE OF RELEASE

Type of Release Produced fluids	Volume of Release 40bbls	Volume Recovered 20bbls
Source of Release Knock out and clean out on tank.	Date and Hour of Occurrence 03-12-2013	Date and Hour of Discovery 03-12-2013 12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 03-18-2013 10:58am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Knock out and clean out gasket failed. Replaced with a hi pressure gasket.		
Describe Area Affected and Cleanup Action Taken.* Initially 40bbls of produced fluid were released. We were able to recover 20bbls of fluid with a vacuum truck. All free fluid has been recovered. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor: Signed By	
Printed Name: Josh Russo	APR 05 2013	Expiration Date:
Title: Senior Environmental Coordinator	Approval Date:	Attached <input type="checkbox"/>
E-mail Address: jrusso@concho.com	Conditions of Approval:	
Date: 03-22-2013 Phone: 432-212-2399		

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

May 5, 2013

2RP-1596