

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

*Amended*

**RECEIVED**  
MAR 13 2013  
NMOCD ARTESIA

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*RJM/W 1308633738* OPERATOR  Initial Report  Final Report

Name of Company	Devon Energy Production Co LP <i>6137</i>	Contact	Ralph Montoya
Address	PO Box 250, Artesia, NM 88211	Telephone No.	575-748-9935
Facility Name	Lava Tube 27 State #1	Facility Type	

Surface Owner	State of New Mexico	Mineral Owner		Lease No.	
---------------	---------------------	---------------	--	-----------	--

**LOCATION OF RELEASE**

*\*API: 30-015-4078*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	34	21S	31E	1015	NORTH	1655	EAST	EDDY

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	BRINE WATER	Volume of Release	350 BBLS	Volume Recovered	320 BBLS
Source of Release	3 SIDED CUTTINGS TANK	Date and Hour of Occurrence	3/9/2013, 4:40 AM	Date and Hour of Discovery	3/9/2013, 4:40 AM
Was Immediate Notice Given?	LEFT MESSAGE ON PHONE <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	RANDY DADE / OCD / ARTESIA, NM		
By Whom?	GUY EMBRY, CONTRACT DRILLER	Date and Hour	3/9/2013, 9:30 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
BERM GAVE AWAY ON 3-SIDED CUTTING TANK, SCRAPING AREA TO RECOVER LAST 30 BBLS.

Describe Area Affected and Cleanup Action Taken.\*  
1) 40' X 30', 2) 50' X 100', 3) 75' X 150', 4) 160' X 25'

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ralph Montoya</i> <i>3-13-13</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: RALPH MONTOYA	Approved by District Supervisor: _____	Signed By: <i>Mike Deacon</i>
Title: DRILLING SUPERINTENDENT	Approval Date: <b>MAR 27 2013</b>	Expiration Date: _____
E-mail Address: Ralph.Montoya@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/13/2013 Phone: 575-748-9935	Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

*April 27, 2013* *2RP-1589*

\* Attach Additional Sheets If Necessary