

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

APR 22 2013

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
NMOCD ARTESIA

Form C-141  
Revised August 8, 2011

Release Notification and Corrective Action

n JMW 13113.35700

Name of Company Burnett Oil Co. 3080		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address Box 188 Loco Hills, NM		Contact Belton Mathews	
Facility Name Gissler A - Inj. Line		Telephone No. 575-677-2313	
		Facility Type Salt Water Inj. Line	
Surface Owner BLM	Mineral Owner	API No. 30-015-30275	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	23	17S	30E					Eddy

Latitude 33 49 434 Longitude 103 56 208

NATURE OF RELEASE

Type of Release Salt Water	Volume of Release 600 to 800 bls	Volume Recovered 400 bls
Source of Release 4 in. injection line broke	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher OCD 4/18/13	
By Whom? Eddie Seay	Date and Hour 4/19/13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

4 in. poly injection line parted, salt water ran down hill and into a pipeline ditch belonging to Holly Energy.

Describe Area Affected and Cleanup Action Taken.\*

From leak - down approximately 400 ft. - 4 to 6 ft. wide, puddled up in an area 25 x 75 and into Holly ditch approximately 225 ft. long. Line was repaired and all available water vacuumed up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Eddie W. Seay	Signed By  Approved by Environmental Specialist	
Title: Agent	Approval Date: APR 23 2013	Expiration Date:
E-mail Address: seay04@leaco.net	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/19/2013 Phone: 575-392-2236		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

MAY 23, 2012

2RP-1632