Submit 1 Copy To Appropriate District Office State of New Mexico District II - (575) 393-6161 Energy, Minerals and Natural Resource 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS Santa Fe, NM 87505 (Do NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other P&A 2. Name of Operator Yates Petroleum Corporation Sunda Fe, NM	WELL API NO. 30-015-00096 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name
 Address of Operator South Fourth Street, Artesia, NM 88210 	10. Pool name or Wildcat Eagle Creek; San Andres
4. Well Location South Line and 1980 feet from the East line Section 14 Township 17S Range 25E NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3479'GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL DOWNHOLE COMMINGLE MULTIPLE COMPL	
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 4/30/13 – MIRU. NU BOP. RIH with bit and scraper to 1300'. Set 7" CIBP at 1230'. Pumped 220 sx Class "C" Neat cement. WOC. 5/1/13 – Tagged plug at 410'. Pumped 75 sx Class "C" Neat cement. Circulated to surface. ND BOP. Topped out casing. Dug out around casing by hand. Thought they saw 10-3/4" casing. Pumped 100 sx to fill up – no fill. Dug down 10'. Found piece of 10-3/4" casing. NOTE: Talked to Randy Dade NMOCD-Artesia. 5/2/13 – Cleaned out around casing. Talked with Randy Dade, suggested we pump water at base of casing to ensure fluids going down around casing, then pump cement to fill up void. He Ok' dhat. Pumped 2 bbls water and it traveled beside casing. Pumped 75 sx Class "C" Neat cement. Void filled up. Watched 20 min, still had cement around casing. Pumped 25 more sx cement in cellar. Took pictures throughout pumping, presented to Randy Dade and was approved. 5/7/13 – Cut off wellhead and installed dry hole marker. Filled cellar. WELL IS PLUGGED AND ABANDONED File Current C103 P&A for final inspection Spud Date: Rig Release Date: Rig Release Date: 	
I hereby certify that the information above is true and complete to the best of my know	avalada and haliaf
SIGNATURE	