District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action													
nJMh	13140		OPERATOR Initial Report Final Rep										
Name of Co			Contact Albert Maes										
Address P			Telephone No. (575) 390-0405 Facility Type Emulsion Line Release										
Surface Ow	ner Bogle	Lease No.											
							NOF RELEASE 4PI#30-015-2/734					17	
Unit Letter	Section	Township	Range	Feet from the	North/South Line		Feet from the	East/V	Vest Line	County			
K&L	34	17S	28E	1,687		FSL	1,348	F	WL	Eddy			
Latitude Longitude													
NATURE OF RELEASE													
Type of Release Oil and Produced Water							Volume of Release 300 barrels Volume Recovered 190 barrels						
Source of Release Emulsion Line							Date and Hour of Occurrence: Date and Hour of Discove 4/22/13 3:00 pm 4/23/13 9:00 am					r::	
Was Immediate Notice Given?						4/22/13 3:00 pm							
☐ Yes ☐ No ☐ Not Required						Left message for M. Bratcher							
By Whom? Bruce Baker, RECS							lour 4/23/13 4:40						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercou	irse was Im	pacted, Descri	be Fully.	k		<u> </u>							
If a Watercourse was Impacted, Describe Fully.*													
Devil Constitution of Devil Assistant Tales *													
Describe Cause of Problem and Remedial Action Taken.* A rupture in a 6" fiberglass emulsion line occurred when a rock punctured the line as the site was backfilled.													
A Tupline in a vintergrass chariston line occurred when a rock panetined the line as the site was oakkined.													
RECEIVED													
Describe Area Affected and Cleanup Action Taken.* - Per Brace. W/ RECS:													
Aren affected is 56,308 total 58.74- with 41,142 58.74. being in MAY 07 2013 ods arent pasture. Analytical data has been obtained for preparation NMOCD ARTESIA I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
odsacent pastore. Analytical data has been o							NMOCD ARTECIA						
Thereby certify that the information given above is true and complete to the best of my knowledge and understand that mursuant to NMOON rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the enviror	ment. In ac	ddition, NMO	CD accep	tance of a C-141	eport do	es not relieve	e the operator of r	esponsil	oility for co	mpliance w	ith any	other	
federal, state, or local laws and/or regulations.							OIL CONSERVATION DIVISION						
Signature:													
							Approved by District Supervisor:						
Printed Name: Albert Maes							MAY 2 0 2013						
Title: Production Foreman						Approval Date: Expiration Date:							
E-mail Address: albertmaes@apachecorp.com						Conditions of Approval:							
				Remediation per OCD Rule &									
Date: 5-7-13 Phone: (575) 390-0405 Attach Additional Sheets If Necessary						Guidelines. SUBMIT REMEDIATION 2RP-1/251							
Attach Additional Sheets If Necessary PROPOSAL NO LATER THAN: 2RP-1651 Tune 20, 2013											l.		
•						June.	40, 401	کد					