

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 30 2013

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form
NMOCD ARTESIA

Release Notification and Corrective Action

Operator ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	HONEYGRAHAM / GRAHAM NASH	Facility Type	GATHERING LINE

Surface Owner	STATE	Mineral Owner	APIK	Lease No. (API#) 30-15-38488 HG #6 (API#) 30-15-38595 HG #7 Sec 28 → (API#) 30-15-37498 GN #1
---------------	-------	---------------	------	---

LOCATION OF RELEASE Assign to 30-015-38488

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	29	26S	28E					EDDY

Latitude 32 01.178 Longitude 104 06.968

32.019597 NATURE OF RELEASE 104.116122

Type of Release	Produced water	Volume of Release	100bbls	Volume Recovered	40bbls
Source of Release	Gathering line	Date and Hour of Occurrence	04/15/2013	Date and Hour of Discovery	04/15/2013 5:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	04/16/2013 10:41am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A 4" water gathering line fractured possibly due to sun fatigue and age. The 4" gathering line has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially an estimated 100bbls were released due to a fracture in a 4" gathering line in the pasture. We were able to recover 40bbls of produced water using a vacuum truck. The gathering line included the Honey Graham #6&7 and Graham Nash #1. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	Signed By 
Title:	Senior Environmental Coordinator	Approval Date:	Expiration Date:
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	04-30-2013	Phone:	432-661-6601

* Attach Additional Sheets If Necessary

MAY 07 2013
Approval Date: MAY 07 2013
Expiration Date:
Conditions of Approval:
Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:
June 7, 2013
2RP-1647