

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAY 23 2013

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Form C-141  
Revised October 10, 2003

### Release Notification and Corrective Action

nJMW1315050599

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	269324	Contact: Gary Wink
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739
Facility Name: Turner B # 47		Facility Type: Injection

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001505435
------------------------	------------------------	---------------------

#### LOCATION OF RELEASE

Unit Letter B	Section 29	Township 17S	Range 31E	Feet from the 560	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.8112685289551 Longitude: -103.889762406761

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 63 bbls	Volume Recovered: 40 bbls
Source of Release: 3" Victaulic high pressure clamp- steel line	Date and Hour of Occurrence: 05/17/2013 1:00am	Date and Hour of Discovery: 05/17/2013 1:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher- NM OCD Mike Burton-BLM	
By Whom? Gary Wink	Date and Hour 05/17/2013 4:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*: Got alarm call out at Russel Turner injection plant around 1:00am, for Low header discharge pressure. Drove to Injection plant and pressures on headers were on zero, I Obie and Isidro drove around field and found location Turner B #47 where 3" high pressure victaulic clamp had blown off steel line.

Describe Area Affected and Cleanup Action Taken.\*: From leak source East to West the impacted area is 20' x 170' all on location inside berm. From leak source outside berm from East to North West impacted area is 3' x 806', this impacted area was in arroyo. Replaced all high pressure Victaulic clamps and rubbers on steel line and return to injecting.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Gary W. Wink	OIL CONSERVATION DIVISION	
Printed Name: Gary W. Wink	Approved by District Supervisor:	Signed By: Mike Bratcher
Title: Production Foreman	Approval Date: MAY 30 2013	Expiration Date:
E-mail Address: gawink@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/23/2013 Phone: 575-390-3477	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

\* Attach Additional Sheets If Necessary

June 30, 2013

2RP-1668