

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JUL 12 2013
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

JMW 1319739260

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	W D MCINTYRE C #002	Facility Type	MAINLINE

Surface Owner	FEDERAL	Mineral Owner		Lease No. (API#)	30-015-04226
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	20	17S	30E					EDDY

Latitude 32 49.912 Longitude 103 57.544

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	332bbls	Volume Recovered	330bbls
Source of Release	6" mainline	Date and Hour of Occurrence	07-08-2013	Date and Hour of Discovery	07-08-2013 5:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD / James Amos - BLM		
By Whom?	Michelle Mullins	Date and Hour	07-10-2013 10:43am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

While installing another pipeline a Trackhoe struck a 6" mainline.

Describe Area Affected and Cleanup Action Taken.*

Initially 332bbls of produced water was released from a 6" main line. We were able to recover 330bbls with vacuum trucks. The spill area was mainly contained in a 30'x5' trench and a run off area of 40'x5'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present the NMOCD/BLM with a work plan for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by District Supervisor:		Signed By: <i>Mike Bratcher</i>
Title: Senior Environmental Coordinator	Approval Date: JUL 16 2013	Expiration Date:	
E-mail Address: rgrubbs@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 07-10-2013 Phone: 432-661-6601	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:		

August 16, 2013 *2RP-1726*

* Attach Additional Sheets If Necessary