

RECEIVED
 JUL 10 2013
NMOCD ARTESIA

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011
 Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NJMW139134649

Name of Company: Mewbourne Oil Company <i>14744</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: PO Box 5270 Hobbs, NM, 88241		Contact: Zack Thomas		
Facility Name: Delaware Ranch SWD		Telephone No. (575) 602-2188		
		Facility Type: Disposal		
Surface Owner: Private	Mineral Owner: N/A	API No. 30-015-22734		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	11	26S	28E	660	South	660	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Overflow	Volume of Release: 50 bbls	Volume Recovered: 0 bbls
Source of Release: Tank thief hatch	Date and Hour of Occurrence: 7-3-13	Date and Hour of Discovery: 7-3-13
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? George Brantley	
By Whom? Zack Thomas	Date and Hour: 7-5-13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
SWD Pump did not kick on automatically therefore tanks were ran over. When pumper arrived on location he immediately started swd pump which stopped the leak.		
Describe Area Affected and Cleanup Action Taken.*		
Leak contaminated a 150 ft by 25 ft area west of the tank containment. All fluids stayed on the pad. Contaminated soil will be excavated and hauled to local land.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Zack Thomas</i>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist:	Signed By: <i>Mike Brantley</i>
Title: Environmental Rep	Approval Date: 1 6 2013	Expiration Date:
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: JUL 16 2013	Attached <input type="checkbox"/>
Date: 6-19-13	Phone: (575) 602-2188	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
 Guidelines. **SUBMIT REMEDIATION
 PROPOSAL NO LATER THAN:
 August 16, 2013**

2RP-1723