


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW1319736064 OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Gary Wink
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575738-1739
Facility Name: Skelly B Battery Satellite # 5 - Skelly 276	Facility Type: Satellite

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001529225
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter D	Section 27	Township 17S	Range 31E	Feet from the 687	North/South Line North	Feet from the 1183	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.8109503533785 Longitude: -103.862221362993

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 3bbls / 2bbls	Volume Recovered: 0 / 0
Source of Release: Poly pipeline	Date and Hour of Occurrence: 06/17/2013 1:00pm	Date and Hour of Discovery: 06/17/2013 1:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher - NM OCD Mike Burton-BLM	
By Whom? Gary Wink	Date and Hour 07/11/2013 3:50pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Got a phone call from roustabout at about 1:00pm and told me I had a flowline leak. So I went to check it out and I had a leak in the middle of Taylor Draw just south of Skelly Unit #276 walked out the flowline and it went to Satalite #5 transfer pump. Had BSG Roustabout fix the leak and we lost about maybe 5 barrels of fluid total. Cost for the day is about 300 dollars.

Describe Area Affected and Cleanup Action Taken.* : Impacted area is about 10'X15'.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gary W. Wink</i>	OIL CONSERVATION DIVISION	
Printed Name: Gary W. Wink	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title: Production Foreman	Approval Date: JUL 16 2013	Expiration Date:
E-mail Address: gawink@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/11/2013 Phone: 575-390-3477	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

August 16, 2013

2RP-1724

* Attach Additional Sheets If Necessary