

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nTJW/1319637807*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher	
Address 104 S. 4 <sup>TH</sup> Street		Telephone No. 575-748-1471	
Facility Name Louise AYI #2	API Number 30-015-33938	Facility Type Battery	
Surface Owner Fee	Mineral Owner Fee	Lease No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	25	21S	26E	990	North	1550	East	Eddy

Latitude 32.45514 Longitude 104.24217

**NATURE OF RELEASE**

Type of Release Produced water mixed with fresh water	Volume of Release 48 B/PW	Volume Recovered 130 B/PW and B/FW Mix
Source of Release Produced water tank	Date and Hour of Occurrence 6/20/2013; PM	Date and Hour of Discovery 6/20/2013; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 6/21/2013; AM	<b>NMOCD ARTESIA</b>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

**RECEIVED**  
JUL 05 2013

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Lightning struck fiberglass produced water tank. Emergency equipment called to put out fire. Vacuum trucks called.

Describe Area Affected and Cleanup Action Taken.\*  
An approximate area of 20' X 40' (inside lined/betmed battery), approximate area of 15' X 25' (outside of battery), and area affected caused by lined battery being filled with fresh water to extinguish fire and overflowed (unknown amounts of PW/FW mix). Liner integrity intact. Vertical and horizontal delineation samples outside of battery will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the OCD. **Depth to Ground Water: <50' (40', Section 25, T21S-R26E, of the NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 20.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Asher</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title: NM Environmental Regulatory Supervisor	Approval Date: <b>JUL 15 2013</b>	Expiration Date:
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	Attached <input type="checkbox"/>
Date: Friday, July 05, 2013 Phone: 575-748-4021	<b>August 15, 2013</b>	

**ZRP-1718**

\* Attach Additional Sheets If Necessary