


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*JMW1319653044* OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	CLUSTER STATE COM #001H	Facility Type	TANK BATTERY
Surface Owner	STATE	Mineral Owner	
		Lease No. (API#) 30-015-37547	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	26S	27E					EDDY

Latitude 32.04866 Longitude 104.20266

**NATURE OF RELEASE**

Type of Release	Oil	Volume of Release	80bbbls	Volume Recovered	79bbbls
Source of Release	Oil tank	Date and Hour of Occurrence	07-06-2013	Date and Hour of Discovery	07-06-2013 10:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	07-08-2013 8:17am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Oil was turned in and expected to be hauled off. The haul truck only hauled off two loads when eight was needed. Follow up with the trucking company to make sure that the proper amounts of fluids have been hauled off.

Describe Area Affected and Cleanup Action Taken.\*

Initially 80bbbls were released from an overflowing oil tank we were able to recover 79bbbls with a vacuum truck. The release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed from the facility and has been replaced with fresh gravel. The facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: <i>Mike Bratcher</i>	
Title: Senior Environmental Coordinator		Approval Date: JUL 15 2013	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	
Date: 07-09-2013 Phone: 432-661-6601		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

*ZRP-1720*