


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011  
This report is filed in the appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nJMW1319333284*

Name of Company <b>Chevron USA Inc. 4323</b>		Contact <b>David A. Pagano</b>	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address <b>15 Smith Rd., Midland, TX, 79705</b>		Telephone No. <b>wk: 575-396-4414X275</b>	cell: <b>505-787-9816</b>
Facility Name <b>TexMack BTY</b>		Facility Type <b>Oil Production Batteries</b>	
Surface Owner <b>Federal</b>	Mineral Owner <b>Federal</b>	API No. <b>30-015-29720</b> ) Closest Well <b>Texmack 11-1)</b>	

Latitude: 32.853570 / Longitude: -103.843080

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	11	17S	31E	990	North	1650	West	Eddy

**NATURE OF RELEASE**

Type of Release <b>Vent</b>	Volume of Release <b>150MSCF/day</b>	Volume Recovered <b>0 MSCF</b>
Source of Release <b>Vent</b>	Date and Hour of Occurrence <b>06/26/13 10:00AM</b>	Date and Hour of Discovery <b>06/26/13 10:00AM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\* N/A  
Describe Cause of Problem and Remedial Action Taken.\*  
VRU is down at the battery due to the motor failing. Chevron Operations is waiting on a replacement motor and expect to have motor replaced by 7/10/13.

Describe Area Affected and Cleanup Action Taken.\* *Locations include: Texmak 11 Fed 10, 11, 15, 27, 28, 32, 39, 41, 42, 57, 61, 63. Per Email dated 7-2-13*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>David Pagano</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>David A. Pagano</b>	Approved by Environmental Specialist:	<b>Accepted for record NMOCD</b>
Title: <b>Health &amp; Environmental Specialist</b>	Approval Date: <b>JUL 12 2013</b>	Expiration Date:
E-mail Address: <b>dpgn@chevron.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>07/02/13</b> Phone: <b>505-787-9816</b>	<b>Like approval by BLM</b>	

\* Attach Additional Sheets If Necessary

*2RP-1714*

Accepted for record  
NMOCD