

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-33979 <i>X 015-40580</i>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Chevron USA, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 15 SMITH ROAD MIDLAND, TX 79705		7. Lease Name or Unit Agreement Name PLU PIERCE CANYON 17 24 30 USA <i>015-40580</i> <i>Ross Ranch 21 25 30 USA</i>
4. Well Location Unit Letter D : 125' feet from the North line and 400' feet from the West line Section 21 Township 25 S Range 30 E NMPM County EDDY		8. Well Number 1H
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3241' GL		9. OGRID Number 4323
		10. Pool name or Wildcat CORRAL CANYON; BONE SPRING, SOUTH

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐



OTHER: ☐

OTHER: Casing Pressure Test ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please find casing pressure tests performed on this well:

On 09/11/2012, tested 13 3/8" surface casing for 30 minutes to 1200 psi. Test good. Depth 455'
On 09/15/2012, tested 8 5/8" intermediate casing for 30 minutes to 1500 psi. Test good. Depth 3500'.
Tested 5 1/2" production casing for 30 minutes to 2000 psi. Test good. Depth 12,560'.



Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Bryan Arrant* TITLE Regulatory Specialist II DATE 12/20/2012

Type or print name Bryan G. Arrant (Agent for Chevron) E-mail address: bryan.arrant@chk.com PHONE: (405)935-3872

For State Use Only

APPROVED BY: *JDade* TITLE Dist. Reg. Supervisor DATE 12/26/2012

Conditions of Approval (if any):

JDade File Corrected July 23, 2013