

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JUL 29 2013
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW 1321048564

OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>192463</i>	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Comanche 3 Federal #1	Facility Type	

Surface Owner	BLM	Mineral Owner		API No.	30-015-28720
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	3	21S	23E	1650	North	1850	East	Eddy County, NM

Latitude N 32.50486° Longitude W 104.59051°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	0.5 bbls oil and 25 bbls produced water	Volume Recovered	0 bbls
Source of Release	Failure in 4" poly production line	Date and Hour of Occurrence	07/04/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Jean Marie Warren- OCD, James Amos and Jennifer VanCuren- BLM.		
By Whom?	Christopher Jones	Date and Hour	07/05/2013 @ 5:11 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Failure of a 4" poly production flow line caused 0.5 bbls of oil and 25 bbls of produced water to leak onto the ground. No fluids were recovered. The line was repaired.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 60' x 25'. Remediation will be completed in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 


Printed Name: Christopher Jones

Title: HES Specialist

E-mail Address: Christopher.Jones@oxy.com

Date: *7-29-13* Phone: (575) 628-4121

OIL CONSERVATION DIVISION

Approved by District Supervisor: Signed By 

JUL 29 2013

Approval Date: _____ Expiration Date: _____

Conditions of Approval:
Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION**

Attached

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
August 29, 2013 *2RP-1766*