

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
AUG 16 2013
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

njmw1323448295

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 105 S. 4 TH Street	Facility Name Bodacious BSM Federal #1-H	Telephone No. 575-748-1471
Facility Name Bodacious BSM Federal #1-H	API Number 30-015-41158	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. NM-113937
------------------------	------------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	I	26S	26E	510	South	660	West	Eddy

Latitude 32.06567 Longitude 104.25284


NATURE OF RELEASE

Type of Release Crude Oil/Condensate	Volume of Release 10 B/O	Volume Recovered 0 B/O
Source of Release Hole in new tank	Date and Hour of Occurrence 8/6/2013; AM	Date and Hour of Discovery 8/6/2013; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*
Hole in new tank being produced into. Had truck transfer production into another tank.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 15' X 25' (inside bermed and lined battery). No oil/condensate recovered, all 10 bbls soaked into chert, entrained in base course material, all impacted material removed and taken to an NMOCD approve facility. New chert/gravel to be put back down. **Depth to Ground Water: > 25' (25", ChevronTexaco Trend Map and 22' per NMOSE, Sec. 8, 26S-26E), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 20. Based on all impacted material removed and battery is lined and liner intact, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor: Signed By 	
Title: NM Environmental Regulatory Supervisor	Approval Date: AUG 22 2013	Expiration Date:
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Thursday, August 15, 2013 Phone: 575-748-4021	Like approval by	

BLM

ZRP-1854

* Attach Additional Sheets If Necessary