

**CHISOS, LTD.**  
670 Doña Ana Road, SW  
Deming, New Mexico 88030  
505 546-8802 - Office  
505 546-7551 - Fax  
[sueanncraddock@zianet.com](mailto:sueanncraddock@zianet.com)

October 5, 2005

Sent Via Facsimile 505 748-9720

New Mexico Energy, Minerals and  
Natural Resources Department  
1301 W. Grand  
Artesia, New Mexico 88210


Re: Wishbone Com NO. 1  
30-015-30640-00-00  
Inspection No. iCLB0521649332

Ladies and Gentlemen:

Please be advised that the remediation required by your letter of August 4, 2005 pertaining to the above referenced well has been completed. If you have any questions or require additional information, please let me know.

Thank you.

Sincerely,



Sue Ann Craddock  
Manager



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Mark E. Fesmire, P.E.**

Director

**Oil Conservation Division**

*Field Inspection Program  
"Preserving the Integrity of the Environment"*

04-Aug-05

**CHISOS, LTD**

670 DONA ANA RD SW

DEMING NM 88030

## NOTICE OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### INSPECTION DETAIL SECTION

**WISHBONE FEDERAL COM No.001**

L-6-19S-30E

**30-015-30640-00-00**

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/04/2005	Routine/Periodic	Chris Beadle	Yes	No	9/6/2005	iCLB0521649332
<b>Violations</b> <b>Surface Leaks/Spills</b>						

**Comments on Inspection:** Location needs attention. Equipment OK. Tank battery has overflowed, soil inside berm contaminated. Remediation Required. Remove contaminated soil and replace with clean fill material. Contact NMOCD District 2 Office when remediation is complete.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By." date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

670 Dona Ana Road, SW  
Deming, New Mexico 88030  
505 546-8802 - office  
505 546-7551 - fax  
sueanncraddock@zianet.com

**Chisos Ltd**

# Fax

**To:** Oil Conservation Division

**From:** Sue Ann Craddock

**Fax:** 505 748-9720

**Pages:** 4

**Phone:**

**Date:** 10/5/2005

**Re:** Wishbone No. 1 Well Remediation

**CC:**

☐ Urgent    ☒ For Review    ☐ Please Comment    ☐ Please Reply    ☐ Please Recycle

• **Comments:**

RBDMS DONE