


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

nJMW1326040559 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Down South State Com #001H	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-41442

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	19	26S	28E					Eddy

Latitude Longitude

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	25bbbs	Volume Recovered	20bbbs
Source of Release	Fitting on transfer pump	Date and Hour of Occurrence	09-05-2013	Date and Hour of Discovery	09-05-2013 5:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOC		
By Whom?	Michelle Mullins	Date and Hour	09-06-2013 3:34pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole developed on the bottom of a 3" Victualic clamp. Replaced the Victualic Clamp with a new one.

Describe Area Affected and Cleanup Action Taken.*

Initially 25bbbs of produced water were released due to a hole that developed on the bottom of the Victualic clamp caused by corrosion. We were able to recover 20bbbs of produced water with a vacuum truck. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed and we have replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: Signed By	
Title: Senior Environmental Coordinator		Approval Date: SEP 17 2013	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09-05-2013 Phone: 432-661-6601			

* Attach Additional Sheets If Necessary

2RP-1910