

District I
1625 N. French Dr., Hobbs, NM 88241
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
OCT 29 2013
WOOD ARTESIA

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

njm 1330255005 OPERATOR Initial Report Final Report

Name of Company Linn Energy 269324	Contact Brian Wall
Address 2130 W. Bender Blvd., Hobbs, NM 88240	Telephone No. (806) 367-0645
Facility Name J.L. Keel A #11	Facility Type Injection Line Release

Surface Owner BLM	Mineral Owner	API No. 3001505099
-------------------	---------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	7	17S	31E	1945	FNL	762	FEL	Eddy

Latitude 32°51'3.227"N Longitude 103°54'10.98"W

NATURE OF RELEASE

Type of Release Production water	Volume of Release 100 bbls	Volume Recovered 15 bbls
Source of Release Injection Line	Date and Hour of Occurrence 8/22/11	Date and Hour of Discovery 8/22/11
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston - BLM	
By Whom?	Date and Hour 8/22/11	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The injection line to the injection well ruptured at the buried 'T' intersection affecting 12,383 sq ft of pasture land. A total of 100 bbls of produced water was released and a total of 15 bbls of produced water was recovered.

Describe Area Affected and Cleanup Action Taken.*
The site will be assessed vertically and horizontally and a Corrective Action Plan will be written with recommendations to remediate the site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Fred B Wall	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by Environmental Specialist:	Signed By: <i>Mike Deacon</i>
Title: Construction Foreman II	Approval Date: OCT 29 2013	Expiration Date:
E-mail Address: Bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	Phone: (806) 367-0645	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

NOVEMBER 29, 2013
2RP-2031

* Attach Additional Sheets If Necessary