


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW1330453408

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 105 South 4th Street, Artesia, NM 88210	Telephone No. 575-748-1471	
Facility Name Amole AMM Battery	API Number 30-015-27314	Facility Type Water Line

Surface Owner State	Mineral Owner State	Lease No. LG-864
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	16	19S	25E	760	South	660	West	Eddy

Latitude 32.65569 Longitude 103.49575

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 4 B/O & 1 B/PW	Volume Recovered 4 B/O & 1 B/PW
Source of Release Heater Treater	Date and Hour of Occurrence 10/10/2013 AM	Date and Hour of Discovery 10/10/2013 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A gasket blew out on a heater treater, causing release (oil and produced water spray). Vacuum truck & roustabout crew called. Valves closed going to heater.

Describe Area Affected and Cleanup Action Taken.*
Area approximately 100' X 80', vacuum truck picked up oil and produced water, impacted pasture area fenced off, back dragged and Micro Blaze sprayed. Pasture will be monitored/checked next spring (2014) to see if any further remediation or revegetation work is needed. **Depth to Ground Water: 50-99' (approximately 95' per New Mexico Office of the State Engineer), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on cleanup actions taken, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor: Signed By	
Title: Environmental Regulatory Agent	Approval Date: OCT 31 2013	Expiration Date:
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: Wednesday, October 30, 2013 Phone: 575-748-4217	2RP-2036	

* Attach Additional Sheets If Necessary

NOVEMBER 30, 2013