

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
OCT 28 2013
NMOCD ARTESIA

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

njmw1330230589

OPERATOR Initial Report Final Report

Name of Company <i>Linn Energy</i> <i>269324</i>	Contact <i>Brian Wall</i>
Address <i>2130 W. Bender Blvd., Hobbs, NM 88240</i>	Telephone No. <i>(806) 367-0645</i>
Facility Name <i>J.L. Keel A #28</i>	Facility Type <i>Flow Line Release</i>

Surface Owner <i>BLM</i>	Mineral Owner	API No. <i>3001528231</i>
--------------------------	---------------	---------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>J</i>	<i>7</i>	<i>17S</i>	<i>31E</i>	<i>2196</i>	<i>FSL</i>	<i>2028</i>	<i>FEL</i>	<i>EDDY</i>

Latitude *32°50'52.24"N* Longitude *103°54'26.222"W*

NATURE OF RELEASE

Type of Release <i>Produced water/Oil</i>	Volume of Release <i>Unknown</i>	Volume Recovered <i>None</i>
Source of Release <i>Break in flow line</i>	Date and Hour of Occurrence <i>Unknown</i>	Date and Hour of Discovery <i>6/27/11</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
While BLM was inspecting another site in the area, BLM discovered a flow line release to the J.L. Keel A #28 injection well. A total of 6762 sq ft of pasture land was affected by the release.

Describe Area Affected and Cleanup Action Taken.*
The site will be assessed vertically and horizontally and a Corrective Action Plan will be written with recommendations to remediate the site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Fred B Wall</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Brian Wall</i>	Approved by Environmental Specialist: Signed By: <i>Mike Benavides</i>	
Title: <i>Construction Foreman II</i>	Approval Date: <i>OCT 29 2013</i>	Expiration Date:
E-mail Address: <i>Bwall@linenergy.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date:	Phone: <i>(806) 367-0645</i>	

PROPOSAL NO LATER THAN:
November 29, 2013 *ZRP-2028*

* Attach Additional Sheets If Necessary