

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1331940873

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy	<i>6137</i>	Contact Roy White	
Address PO Box 250 Artesia, NM 88211		Telephone No. 575- 513-1741	
Facility Name Burton Flat 48		Facility Type Oil	

Surface Owner Federal	Mineral Owner	API No. 30-015-40518
------------------------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter I	Section 28	Township 20S	Range 28E	Feet from the 2310	North/South Line SOUTH	Feet from the 400	East/West Line EAST	County EDDY
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude: 32.5435843 Longitude: -104.1755763

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 200bbls	Volume Recovered None
Source of Release Cracked Valve	Date and Hour of Occurrence 11/6/13 9:00 am	Date and Hour of Discovery 11/6/13 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Rudy Zuniga/Asst Foreman-Roy White/Foreman Don Mayberry/Superintendent-Scott Poe/EHS Jeff Robertson-BLM	
By Whom? Ray Carter	Date and Hour 11/6/13 9:00 am	RECEIVED NOV 13 2013
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*
At the Burton Flat 48H a water transfer line had a cracked valve which caused approximately 200bbls of produced water to spill while transferring from the Burton Flat 47 to the Burton Flat 44.

Describe Area Affected and Cleanup Action Taken.*
At the Burton Flat 48H a water transfer line had a cracked valve which caused approximately 200bbls of produced water to spill into the pasture while transferring from the Burton Flat 47 to the Burton Flat 44. On 11/5/13 while pressuring up and filling up a water transfer line from Burton Flat 47 to the Burton Flat 44 SWD the line pressured up to about 120pounds and the line stayed flowing. Pressure was lost pressure so everything was shut everything down and enclosed the valve. While it was running approx. 400bbls went down the line and in trying to figure out if it was a pump problem or a line problem Ray Carter came across part of the line that had not been visibly inspected and noticed a valve was cracked open. When line pressured up it blew the plug and that is why pressure was lost and caused the spill. Approximately 200bbls PW went into the pasture...that is where the line is. None was recovered. Called Talon for testing and clean out.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Veronica Teel</i>	OIL CONSERVATION DIVISION	
Printed Name: Veronica Teel	Approved by Environmental Specialist	Signed By <i>Mike Bernice</i>
Title: Field Admin Support	Approval Date NOV 15 2013	Expiration Date:
E-mail Address: Veronica.Teel@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/8/13 Phone: 575-748-9933	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
December 15, 2013

2RP-2065