

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 01 2013

Form C-141
Revised October 10, 2003

NMOC DISTRICT OFFICE IN
ARTESIA, NM
appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW1331041969

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly # 33	Facility Type: Injection

Surface Owner: Federal	Mineral Owner:	API No.: 3001505140
------------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	14	17S	31E	660	South	660	West	Eddy

Latitude: 32.8291697037487 Longitude: -103.846783622658

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 130 bbls	Volume Recovered: 10 bbls
Source of Release: Steel Pipeline	Date and Hour of Occurrence: 10/04/2013 8:30am	Date and Hour of Discovery: 10/04/2013 8:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton-BLM Mike Bratcher- NM OCD	
By Whom? Brian Wall	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: bad collar on 2" steel line, collar and joint replaced.

Describe Area Affected and Cleanup Action Taken.*: Excavate contaminated soil and remove to an approved disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Brian Wall*

Printed Name: Brian Wall

Title: Construction Foreman II

E-mail Address: bwall@linenergy.com

Date: 11/01/2013

Phone: 806-367-0645

Approved by District Supervisor:

Signed By *Mike Bratcher*

Approval Date:

NOV 06 2013

Expiration Date:

Conditions of Approval:

Attached ☐

Remediation per OCD Rule & Guidelines, &
like approval by BLM. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

December 6, 2013

2RP-2045

* Attach Additional Sheets If Necessary