


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMK 1319333284

| | | |
|--|-----------------------|---|
| Name of Company Chevron USA Inc. 4323 | | Contact David A. Pagano |
| Address 15 Smith Rd., Midland, TX, 79705 | | Telephone No. wk: 575-396-4414X275 cell: 505-787-9816 |
| Facility Name TexMack BTY | | Facility Type Oil Production Batteries |
| Surface Owner Federal | Mineral Owner Federal | API No. 30-015-29720) Closest Well Texmack 11-1) |

Latitude: 32.853570 / Longitude: -103.843080

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| C | 11 | 17S | 31E | 990 | North | 1650 | West | Eddy |

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release Vent | Volume of Release 1800MSCF | Volume Recovered 0 MSCF |
| Source of Release Vent | Date and Hour of Occurrence 06/26/13 10:00AM | Date and Hour of Discovery 06/26/13 10:00AM |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* N/A | | |
| Describe Cause of Problem and Remedial Action Taken.* VRU down at the battery due to the motor failing. After motor replaced the drive malfunctioned and was subsequently repaired. Vented a total of 864hrs and a total of 1,800mcf. | | |
| Describe Area Affected and Cleanup Action Taken.* N/A | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCd rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCd marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCd acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: David Pagano | OIL CONSERVATION DIVISION | |
| Printed Name: David A. Pagano | Approved by Environmental Specialist: | Signed By Mike Brumley |
| Title: Health & Environmental Specialist | Approval Date: SEP 04 2013 | Expiration Date: |
| E-mail Address: dpqn@chevron.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 08/02/13 Phone: 505-787-9816 | | |

* Attach Additional Sheets If Necessary

Closed
SEP 04 2013

2RP-1714