

District I:
1625 N. French Dr., Hobbs, NM 88240
District II:
811 S. First St., Artesia, NM 88210
District III:
1000 Rio Brazos Road, Aztec, NM 87410
District IV:
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

DEC 18 2013

Form C-141
Revised August 8, 2011

NMOCDA ARTESIA
Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1335336548

OPERATOR

X Initial Report ☐ Final Report

Name of Company: Cimarex Energy Company 162683	Contact: Johnny Titsworth
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701	Telephone No. (432)250-2059
Facility Name: Texas 32 State TB	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner:	API No: 30-015-39110
----------------------	----------------	----------------------

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	18	26	330	FNL	990	FWL	Eddy

Latitude: 32.71081 Longitude: 104.40968

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 45 / 45	Volume Recovered: 45 / 45
Source of Release: FWKO	Date & Hour of Occurrence: 12/17/13 0700	Date & Hour of Discovery: 12/17/13 0800
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? James Tinney	
By Whom? Nippy Howard	Date and Hour: 12/17/13 0800	
Was a Watercourse Reached? X Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Gasket on FWKO (free water knock-out) leaked. FWKO was isolated and used a vacuum truck to recover standing fluids.		
Describe Area Affected and Cleanup Action Taken.* Majority of spill was contained inside lined facility, with a 200'x200' overspray area on the pad, and a 100'x100' overspray area in the pasture. Pad area has been scraped and the impacted soil will be hauled to disposal, pasture area will be micro-blazed to neutralize hydrocarbons.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: Signed By: 	
Printed Name: Johnny Titsworth	Approval Date: DEC 19 2013	Expiration Date:
Title: Environmental Compliance Coordinator	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
E-mail Address: jtitsworth@cimarex.com	Attached <input type="checkbox"/>	
Date: 12/18/13	Phone: (432)-250-2059	

* Attach Additional Sheets If Necessary

JANUARY 19, 2013

2RP-2124